


Handverschraubungen


Handverschraubung : Außengewinde



Standard M22 : AG. Schwarz.
Max. 400 bar / 150 °C



Standard M21 : AG. Grau.
Max. 400 bar / 150 °C




Kurz M22 : AG. Schwarz.
Max. 400 bar / 150 °C

AG
1/4"
3/8"
1/2"
M14
M16
M18
M21
M22


R+M Nr.	I
561 40	49 mm
561 60	46 mm
561 66	50 mm
561 70	51 mm
561 80	51 mm
561 90	47 mm
561 98	49 mm
561 95	60 mm

R+M Nr.	I
564 20	44 mm
564 40	45 mm
564 50	43 mm
564 62	49 mm
564 60	60 mm

R+M Nr.	I
560 30	28 mm



Kurz M21 : AG. Grau.
Max. 400 bar / 150 °C



Kurz M22 : AG. Edelstahl.
Max. 400 bar / 150 °C




Kurz PG 13,5 : AG.
Max. 400 bar / 150 °C

AG
1/4"

R+M Nr.	I
563 20	27 mm

R+M Nr.	I
560 39	28 mm

R+M Nr.	I
560 60	28 mm




M22 : AG. Edelstahl. Max. 500 bar


AG
1/4"
3/8"

R+M Nr.	I
561 49	48 mm
561 69	45 mm


Handverschraubung : Handverschraubung



HV M22 : HV M22.
Max. 400 bar / 150 °C



HV M22 : HV M21.
Max. 400 bar / 150 °C



HV M21 : HV M21.
Max. 400 bar / 150 °C

⊙

R+M Nr.	I
561 96	50 mm

R+M Nr.	I
561 97	50 mm

R+M Nr.	I
564 65	65 mm